

Store Asbestos Locator

***** EXAMPLE DOCUMENT HELD IN EACH STORE THAT CONTAINS ASBESTOS *****

Asbestos is a substance which has been used widely in buildings, mainly due to its properties of fire proofing. Thousands of buildings such as this one built before 1985 contain asbestos, which is absolutely safe unless it is damaged, causing the release of inhalable asbestos fibres.

The information given below shows where asbestos has been used in this store. It is regularly checked to ensure it is in safe condition. The general maintenance and specialist contractors such as Parkersell are aware of where asbestos is, and have procedures for safe working.

It is important that contractors are referred to this document before carrying out work. If any asbestos is damaged or further advice is needed, immediately contact the help desk on: 01895 863400.

Contractors must not carry out any work on asbestos without using the asbestos permit to work procedure, the only exception being Parkersell, who are working under an agreed 'Safe System of Work'.

Location of asbestos in this store, is as follows:

STORE:	XXXX		
FLOOR	LOCATION	DESCRIPTION	TYPE OF MATERIAL
Ground	Stairwell (19)	Ceiling tiles	Board
Ground	Lift motor room (22)	Electric boxes	Presumed to contain Chrysotile woven fuse gaskets
Ground	Unloading bay (23)	Electric boxes	Presumed to contain Chrysotile woven fuse gaskets

Health & Safety Procedures

FLOOR	LOCATION	DESCRIPTION	TYPE OF MATERIAL
Ground	Unloading bay (23)	Door head panel over door to van stand area	Board
Ground	Van standing area (25)	Internal lining panels at height to perimeter walls	Board
Ground	Security store (27)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Male cloakroom (30)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Male cloakroom (30)	Window reveals	Board
Ground	Male toilets (31)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Female toilets (33)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Male toilets (31)	Window reveals	Board
Ground	Female toilets (33)	Window reveals	Board
Ground	Meat prep. area (35)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Meat prep. area (35)	Bulk head over fridge	Board
Ground	A.T.M. security sensitive area (8)	Wall panels above suspended ceiling	Board
Ground	Processor room (12)	Ceiling tiles	Board
Ground	Entrance lobby (1)	Ceiling tiles	Board
Ground	Sales area (2)	Ceiling tiled around shop floor	Board
Ground	Sales area (2)	Casing to duct in ceiling void over tills area	Board
Ground	Sales area (2)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Exit lobby (3)	Ceiling tiles	Board
Ground	Exit lobby (3)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Storage area (4)	Ceiling tiles	Board

Health & Safety Procedures

FLOOR	LOCATION	DESCRIPTION	TYPE OF MATERIAL
Ground	Storage area (4)	Electrical boxes	Presumed to contain Chrysotile woven fuse gaskets
Ground	Corridor (5)	Ceiling tiles	Board
Ground	Cash office (10)	Window reveals	Board
Ground	Managers office (9)	Window reveals	Board
Ground	Managers office (9)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Cash office (10)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	General Office (11)	Window reveals	Board
Ground	General office (11)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Processor room (12)	Ceiling tiles	Board
Ground	Cold store (13)	Internal lining panels at height to perimeter walls in ceiling void	Board
Ground	Bulk stock area (18)	Electric box	Presumed to contain Chrysotile woven fuse gaskets
Ground	Bulk stock area (18)	Ceiling tiles	Board
First	Boiler room (53)	Electric boxes	Presumed to contain Chrysotile woven fuse gaskets
First	Ladies cloakroom (57)	Toilet cistern	Plastic
First	Ladies cloakroom (57)	Ceiling tiles	Board
First	Ladies cloakroom (57)	Wall panel to rear of sink	Board
First	External – above windows (59)	Soffit, extends to area inside store, behind windows	Board
First	Plant room (52)	Wall panel	Board
First	Boiler room (53)	Seals	Insulation

Health & Safety Procedures

FLOOR	LOCATION	DESCRIPTION	TYPE OF MATERIAL
First	Electric gantry (41)	Internal lining panels at height to perimeter walls in ceiling void	Board
First	Electric gantry (41)	Electric boxes	Presumed to contain Chrysotile woven fuse gaskets
First	Plant room (42)	Electric boxes	Presumed to contain Chrysotile woven fuse gaskets
First	Plant room (52)	Electric boxes	Presumed to contain Chrysotile woven fuse gaskets
First	Plant room (52)	Pipework gaskets	Presumed to contain Chrysotile woven fuse gaskets