



Mixing UV-curable inks

COSHH essentials for printers

This information is intended to help employers in the printing industry comply with the requirements of the Control of Substances

Hazardous to Health Regulations 2002 (COSHH), as amended, to control exposure to chemicals and protect workers' health.

It is also useful for trade union safety representatives.

This sheet describes good practice for mixing UV-curable inks used in smaller-scale printing operations.

It is important to follow all the points or use equally effective measures.

Main points

- Avoid skin contact with UVcurable inks - these can cause dermatitis.
- Carry out health surveillance for dermatitis.
- Check the supplier's safety data sheet - the ink should conform to the 'Acrylate Preference Criteria'.
 If not, seek advice from your supplier.

Flexographic printing

Access and premises

- ✓ Only allow authorised staff access to the mixing room.
- ✓ Provide good facilities for washing, skin care, and for taking refreshments.

Equipment

- Provide a good standard of general ventilation. Use powered wall- or window-mounted fans to supply fresh air - five to ten air changes per hour, with a through draught.
- ✓ Can you use pumped ink transfer systems?
- Can you avoid mixing by pumping the chemicals to the applicator head?
- ✓ Provide chemical-resistant gloves.
- ✓ Use UV-curable inks and coatings that conform to the Acrylate Preference Criteria.
- ✓ Stand containers in shallow trays to contain spills.

Maintenance, examination and testing

- ✓ Follow the instructions in the maintenance manual keep equipment in effective and efficient working order.
- ✓ Noisy or vibrating fans indicate a problem. Do repairs as necessary.
- ✓ Check transfer hoses and connectors regularly for leaks.

Personal protective equipment (PPE)

✓ Provide storage for PPE to prevent damage or contamination when not in use.

Respiratory protective equipment (RPE)

Respiratory protective equipment should not be needed for routine use.

Gloves

- ✓ Use chemical resistant gloves nitrile gloves 0.4 mm thick are acceptable. These are suitable for splash protection only, for no more than 30 minutes.
- ✓ Ensure that workers wear them.
- Minimise hand-wiping
- ✓ Ensure workers remove and discard damaged gloves.

Other protective equipment

- Eye protection.
- Impervious apron.
- ✓ Cotton overalls to minimise clothing contamination.
- Change contaminated overalls immediately and ensure they are laundered before reuse.

Skin management

✓ Skin contact with UV-curable inks and coatings may cause dermatitis.

Skin care

- ✓ Keep hands clean and in good condition.
- Using pre-work creams helps make removing chemicals easier. However, pre-work creams should not be seen as a substitute for gloves.
- ✓ If you need to use hand cleansers to remove ink, ensure that the cleanser is rinsed off afterwards.
- ✓ Provide after-work creams (moisturisers) to replace skin oils.
- ✓ Never allow solvents to be used for cleaning skin.

Skin surveillance/checks

- ✓ Health surveillance for dermatitis is required. See sheet P45.
- Seek advice from an occupational health professional in setting up a health surveillance programme.
- ✓ Start surveillance for new workers within six weeks of their starting work. Then check at monthly intervals or as advised by your health professional.

Cleaning and housekeeping

- ✓ Keep the work area tidy, clean and free of ink contamination.
- Clean the workroom at least once a week.
- ✓ Handle containers with care and replace caps. Wipe off any liquid on the outside of the container.
- ✓ Clean up spills immediately. Use an impervious apron and new nitrile gloves 0.4 mm thick. Throw away gloves once used.
- ✓ Store contaminated cloths, wipes and gloves in fire-resisting, closed, metal containers. Dispose of them as hazardous waste.
- ✓ Dispose of waste solvent, ink and empty containers as hazardous waste.
- ✓ Use a contract laundry or a suitable equivalent to wash work clothing. Don't do this at home.

Training and supervision

- ✓ Working in the right way is important for exposure control. Train and supervise workers - see details in sheet P0.
- ✓ Warn about the dermatitis risk from UV-curable inks.

Environmental guidelines

Releases into the air may be regulated within the Pollution Prevention and Control (PPC) framework. Your local authority or the Environment Agency will tell you if PPC applies to your company, and give advice on air cleaning and discharging emissions to the air. In Scotland, consult the Scottish Environment Protection Agency (SEPA). For more information, see http://www.environment-agency.gov.uk/netregs/sectors/.

Further information

- The printer's guide to health and safety (Second edition)
 HSE Books 2002 ISBN 0 7176 2267 3
- Skin problems in the printing industry Leaflet IACL101(rev1)
 HSE Books 2002 (single copy free or priced packs of 15
 ISBN 0 7176 2322 X)
- General ventilation in the workplace: Guidance for employers HSG202
 HSE Books 2000 ISBN 0 7176 1793 9

Useful links

Contact the British Occupational Hygiene Society (BOHS) on 01332 298101 or at www.bohs.org/ for lists of qualified hygienists who can help you.

Look in Yellow Pages under 'Health and safety consultants' and 'Health authorities and services' for occupational physicians (doctors and nurses). Also see www.nhsplus.nhs.uk/.

This guidance is issued by the Health and Safety Executive. Following the guidance is not compulsory and you are free to take other action. But if you do follow the guidance you will normally be doing enough to comply with the law. Health and safety inspectors seek to secure compliance with the law and may refer to this guidance as illustrating good practice.

Employee checklist
☐ Is the workroom ventilation switched on and working properly?
\square Look for signs of wear and damage.
☐ If you find any problems, tell your supervisor or safety/ employee representative. Don't just carry on working.
Wear your protective equipment as directed.
☐ Throw away protective gloves at the end of the job.
☐ Don't use damaged gloves.
Never use solvents to clean your hands - only use proprietary skin cleansers.
Use skin creams provided, as instructed.
Check your skin regularly for dryness or soreness - tell your supervisor if these appear.
Co-operate with health surveillance for dermatitis.
Wash your hands before eating and drinking and before you leave work.
Don't smoke in the work area.