

Breathing isocyanate paint mist causes asthma

- Spraying causes most mist so always use an extracted spray booth/room.
- A lot of the paint mist is normally invisible. It does not smell and spreads through the air like smoke.
- It takes time for fine mist to clear. Find out the booth or room 'clearance time'.



- Anyone exposed to paint mist should use air-fed breathing apparatus. Supplied air must be at the right pressure, filtered and clean.



- **Never** lift your visor or remove your breathing apparatus during clearance.
- Keep everyone else out until the paint mist has cleared.



See online version and more advice: www.hse.gov.uk/mvr/priorities/isocyanates.htm