

Legionella in Aqueous tunnel washers



Review

- Identified new potential source of Legionella
- But conditions are not new and existing controls are applicable
- Sector Information Minute produced with input from industry experts – written for inspectors but free to download

The way forward

- Details in trade press and via trade associations, TUs etc. Stay alert to other applications with similar conditions
- Users need to be aware of risks and take steps to control them
- Design issues need to be addressed by manufacturers
- Water treatment companies to pass on lessons to client companies