

Company name: **LMN Engineering Ltd**
Address: **Unit 3A, Trading Estate West, Anytown XX9 9YY**

ASBESTOS REGISTER

Where	Product	How much?	Surface coating	Condition	How easy access?	Asbestos type	Comment	Material score	Priority score
<u>Outside</u>									
Roof	Asbestos cement	Whole roof	None	Fairly good	Difficult	White?	No sample		
Down-pipe	Asbestos cement	4 x 4 metres	None	One broken	Medium	Don't know = Presumed	No sample		
<u>Inside</u>									
Plant room	Board panels	43 sq metres	Emulsion paint	Good	Easy	Presumed	No sample		
Plant room	Pipe - insulation	15 metres	Gloss paint	Cracked	Medium	Brown	Bit that fell off analysed		
Plant room	Gas boiler	Don't know	Metal case	Don't know	Difficult	Presumed	No sample		
Plant room	Cement flue from boiler	5 metres	None	Good	Medium	White?	No sample		
Plant room	Electrical switch-box	One item	None	Crumbling	Medium	White?	No sample		
Store	Ceiling tiles	72 tiles, 50x50 cm	Emulsion on lower face	Medium	Medium	Presumed	No sample		
Store	Above tiles	18 sq metres	Unknown	Unknown	Difficult	Presumed	No sample		
Store	Cushion floor tiles	6 x 3 m	Vinyl over asbestos paper	Chipped tile by door	Easy	White?	No sample		
Office 1 fire door	Door	4 sq m	None - board in the door	Good	Medium	Presumed	No sample		
Office 2 fire door	Door - board screwed on	4 sq m	Gloss paint	Medium	Easy	Presumed	No sample		
Anneal oven	Asbestos rope	3 m	None	Medium	Easy	White	No sample		
Anneal oven	Asbestos gloves	1 pair	None	Poor	Easy	White	No sample		
<u>Other</u>									
Delivery van	Brakes	4 sets	None	Fair	Difficult	White?	No sample		

Name: T Smith, works engineer Date: 12 December 2007