

Example asbestos register

Company name: LMN Engineering Ltd

Address: Unit 3A, Trading Estate West, Anytown XX9 9YY

Where	Product	How much?	Surface coating	Condition	How easy access?	Asbestos type	Comment	Material score	Priority score
<u>Outside</u>									
Roof	Asbestos cement	Whole roof	None	Fairly good	Difficult	White?	No sample	1	1
Down-pipe	Asbestos cement	4 x 4 metres	None	One broken	Medium	Don't know = presumed	No sample	5	6.2
<u>Inside</u>									
Plant room	Board panels	43 sq metres	Emulsion paint	Good	Easy	Presumed	No sample	1	1
Plant room	Pipe - insulation	15 metres	Gloss paint	Cracked	Medium	Brown	Bit that fell off analysed	8	12
Plant room	Gas boiler	Don't know	Metal case	Don't know	Difficult	Presumed	No sample	7	10.5
Plant room	Cement flue from boiler	5 metres	None	Good	Medium	White?	No sample	1	1
Plant room	Electrical switch-box	One item	None	Crumbling	Medium	White?	No sample	7	10.5
Store	Ceiling tiles	72 tiles, 50x50 cm	Emulsion on lower face	Medium	Medium	Presumed	No sample	5	9.3
Store	Cushion floor tiles	6 x 3 m	Vinyl over asbestos paper	Chipped tile by door	Easy	White?	No sample	5	11.3
Store	Above tiles	18 sq metres	Unknown	Unknown	Difficult	Presumed	No sample	1	1
Office 1 fire door	Door	4 sq m	None - board in the door	Good	Medium	Presumed	No sample	1	1
Office 2 fire door	Door - board screwed on	4 sq m	Gloss paint	Medium	Easy	Presumed	No sample	6	11.7
Anneal oven	Asbestos rope	3 m	None	Medium	Easy	White	No sample	7	14.8
Anneal oven	Asbestos gloves	1 pair	None	Poor	Easy	White	No sample	7	16.2
<u>Other</u>									
Delivery van	Brakes	4 sets	None	Fair	Difficult	White?	No sample	1	1

Name: T Smith, works engineer Date: 12 December 2007

Check date: December 2008